Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2321 Work Order Type: Weatherization **Audit Name: 14014SO2321**

CLIENT INFORMATION

Client Name: 14014SO2321 Address: , Unit 1416

Columbia, TN 38401 Client ID: 14014SO2321

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO2321 Applicant/Person of **V** Record

AGENCY INFORMATION

Agency Phone: (931) 433-7182 **Agency:** South Central Human Resource Agency

Address: 1437 Winchester Highway Fax: (931) 438-0074

> Fayetteville, TN 37334 Email Address:

Agency Contact: Ford, Duane Work Phone:

> Cell Phone: (615) 308-7878 Email Address: Fordd@hughes.net

Company Name & License Number:	
Contractor's Signature	

COMMENT

1 story brick home in good condition. Replace HVAC system. Possible abestos on pipes in attic.

Client Name: 14014SO2321 Client ID: 14014SO2321 Alt. Client ID: Maury

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: 14014SO2321 Version 8.5.0 Report Run On: 5/28/2010 Page 1 of 7

Measures

	Measure	1	Infilt	tration	Redctn						Con	npone	ents	S				Inspecte
Comment 1. Repair water leak in roof. 2. Repair sheetrock in bonus room ceiling. 3. Air seal attic stairway per Field Guide. 4. Construct crawl space door. 5. Repair ductwork and mastic register. 6. Trim out and caulk to air seal top shelf of bookcase in bonus room. 7. Clear caulk crown, corners, jambs, casing, and window seats. 8. Air seal around fireplace. 9. Mastic return air plenum.																		
		•			о р.о.						E	stimat	ed			Act	ual	
#	Material /	La	bor	Descri	ption / Co	omment		Units	Q	t y	Un	it Cost		Total	Qty	Unit	Cost	Total
1	Miscellar Supplies	eo	us	Infiltra	tion Red	uction		Each	1									
2	Labor			Labor				Hour	8	1								
(Other Detai	ı							,									
									Mea	sure	e Sul	Total				Sub To	otal:	
	Field Note	s:																

	_	lace HVAC			Componei	nts HVAC			Inspected
C	Comment				Estimate	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	HVAC- Consult Manual J Data	Each	1					
2	Labor	Labor	Each	1					
(Other Detail			1				1	
L									
				Measur	e Sub Total:			Sub Total:	
[Field Notes:							l	
	Measure 3 DWI	H Pipe Insulation			Componer				Inspected
					Estimate			Actual	
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:							· · · · · · · · ·	

Client Name: 14014SO2321 Client ID: 14014SO2321 Alt. Client ID: Maury

Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0 Page 3 of 7

1		Replace 1 Rottei 36x48	n Window II	n Additio	n	Compone	nts Windo	ow		Inspected
C	omment									
						Estimate	d		Actual	
#	Material / Labo	or Description /	Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Window		Each	1					
2	Labor	Labor		Hour	4					
C	Other Detail									
_					Measur	e Sub Total:]	Sub Total:	
-	Measure 5	DWH Tank Insul	ation			Compone	nts DWH			Inspected
C	omment									
						Estimate	d		Actual	
#	Material / Labo	or Description /	Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank I	nsulation	Each	1					
		R-10 minimu Appendix A- for Weatheri Materials and Field Guide.	Standards zation							
2	Labor	DHW Tank I	nsulation	Each	1					
C	Other Detail									
					Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:									

Client Name: 14014SO2321 Client ID: 14014SO2321 Alt. Client ID: Maury DOE Weatherization Assistant Version 8.5.0 Page 4 of 7

Report Run On: 5/28/2010

Measure 6 Floor	r Ins. R-19			Componen	ts Crawl		1	Inspecte
•	s estimated. Contractor to eas may not be accessible	•	00% co	verage of R	R30 prior	top bid.		
				Estimated	<u> </u>		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1088					
Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1088					
Other Detail								
			Moasura	Sub Total:			Sub Total:	
Field Notes: Measure 7 Fix I	mproper Venting (Cloth				<i>t</i> s Ventir	na		Inspecte
Measure 7 Fix II	mproper Venting (Cloth			Componen		ng		Inspecte
	mproper Venting (Cloth Description / Comment					ng Qty	Actual Unit Cost	Inspecte
Measure 7 Fix II Comment Material / Labor		es Dryer)	Componen Estimated	1		Actual	
Measure 7 Fix In Comment Material / Labor Health and Safety Items	Description / Comment	es Dryer	Qty	Componen Estimated	1		Actual	
Measure 7 Fix In Comment Material / Labor Health and Safety Items Labor	Description / Comment Equipment	es Dryer Units Each	Qty	Componen Estimated	1		Actual	
Measure 7 Fix In Comment Material / Labor Health and Safety Items Labor	Description / Comment Equipment	es Dryer Units Each	Qty	Componen Estimated	1		Actual	
Measure 7 Fix In Comment Material / Labor Health and Safety Items Labor	Description / Comment Equipment	es Dryer Units Each	Qty	Componen Estimated	1		Actual	
Measure 7 Fix II Comment Material / Labor Health and Safety	Description / Comment Equipment	es Dryer Units Each Hour	Qty 1 0.5	Componen Estimated	1	Qty	Actual	

	Measure 8 Pres omment	sure Relief Piping Nee	ded		Componen	ts DWH			Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1					
2	Labor	Labor	Hour	1					
0	ther Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 9 Smo omment	ke/ CO2 Detector Com	bo		Componen				Inspected
C	omment			Otv	Estimated	·	Otv	Actual	
<i>C</i> :		ke/ CO2 Detector Com Description / Comment Smoke/CO2 Detector Combo	Units Each	Qty 1	•		Qty		Inspected
C (#	omment Material / Labor Health and Safety	Description / Comment Smoke/CO2 Detector	Units		Estimated	·	Qty	Actual	
C .# 1	omment Material / Labor Health and Safety Items	Description / Comment Smoke/CO2 Detector Combo	<i>Units</i> Each	1	Estimated	·	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment Smoke/CO2 Detector Combo	<i>Units</i> Each	1	Estimated	·	Qty	Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment Smoke/CO2 Detector Combo	<i>Units</i> Each	1	Estimated	·	Qty	Actual	
C .# 1	omment Material / Labor Health and Safety Items Labor	Description / Comment Smoke/CO2 Detector Combo	Units Each Hour	1	Estimated	·		Actual	
C # 1	omment Material / Labor Health and Safety Items Labor	Description / Comment Smoke/CO2 Detector Combo	Units Each Hour	1	Estimated Unit Cost	·		Actual Unit Cost	

Measure 10 Vapor Barrier Needed (Basement/Crawlspace)					Componen	ı	Inspected		
C	comment								
					Estimated	<u> </u>			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	Each	1					
2	Labor	Labor	Hour	1					
	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work Or	der Gra	nd Total:		Gran	d Total:	